
















- | | | |
|------------------|------------------|-----------------|
| 1 set
L400 mm | 8 x | |
| 4 x
5 x50 | 2 x
7 x50 | 16 x
5x13 |
| 20 x | 12 x | 12 x |
| 2 x
M6x24 | 2 x
Φ8 | 65 x |
| 4 x | 6 x
4,2/25 | 2 x
4/45 |
| 4 x
№11 | 32 x
3,5 / 16 | 4 x
3,5 / 30 |
| 6 x | 4 x
PK | 2 x
OK |
| | | |





3 к-та

50 x [Screw]	12 x 5x10 [Screw]	8 x [Bracket]
12 x [Bracket]	12 x [Screw]	12 x [Bracket]
3 x №11 [Bracket]	18 x 3.5 / 16 [Screw]	6 x 4,2/25 [Screw]
6 x [Bracket]	4 x PK [Bracket]	2 x OK [Bracket]

